| airstrip condition and details with owner |  |   |   |
|---|--|---|---|
| Variation: 1.9°W                          | Mandurah<br>250° (M) 5 nm<br>250° (M) 5 nm<br>250° (M) 5 nm<br>250° (M) 5 nm<br>250° (M) 5 nm  | house<br>house<br>house<br>house<br>house | H <u>Serpentine Airstrip</u><br>H <u>015°(M) 6.7 nm</u> |
| RIGHT CIRCUITS<br>RWY 05 and RWY 09       |  |   |   |
| NORTH TO THE TOP · DRAWING<br>Elevation:  | 90 Feet AMSL Time Zone: UTC + 8  |   |   |
|   | 32° 30' 34" South 115° 49' 52" East  | Avfax Code:                               | 6010  |
| GPS Position:<br>WAC Chart:               |  |   |   |
|   | Albany (3462) ALA Code: YMUL   |   |   |
| Owner/Operator:                           | Royal Aero Club of WA Inc. (08) 95816222, <u>info@royalaeroclubwa.com.au</u>   |   |   |
| Strip Directions:                         | 05-23 09-27  |   |   |
| Strip Lengths:                            | 1143 M 893 M   |   |   |
| Strip Surface:                            | Bitumen Gravel   |   |   |
| Windsock:                                 | Yes  |   |   |
| Strip Markers:                            | White cones  |   |   |
| Lighting:                                 | Runway 05-23 - PAL + AFRU 119.1  |   |   |
| Fuel:                                     | Av 100   |   |   |
| Procedures<br>And Remarks:                | CTAF-AFRU 119.1 (Serpentine also). Perth Centre 135.25 (in the circuit). HF 3461/6565/8822. Beware animal hazard. Beware numerous power lines. Beware parachuting up to F150. Beware low level aerobatics are conducted within 1 NM. The runway 05 threshold is displaced. Right hand circuits runway 05 and runway 09. Take off runway 27 not permitted except emergency. Noise abatement procedures apply (check with RACWA). Circuit training permitted only between 0700 and 2200 LMT, limited to aircraft not exceeding 200 HP. Caution: edges are soft, remain on the hard surfaces at all times. Turn only at the runway ends. Helicopter operations not permitted RWY 09/27 or west of RWY 05/23. Permission required prior to use (08) 95816222 (ARO), (08) 94170000 (Operations). Cross check details with ERSA. |   |   |
| <u> </u>                                  |  |   |   |

## Murray Field (Mandurah), WA