


Warning: It is a requirement to check  
airstrip condition and details with owner

# Maryborough, VIC



NORTH TO THE TOP - DRAWING NOT TO SCALE

<b>Elevation:</b>	778 Feet AMSL	<b>Time Zone:</b>	UTC + 10
<b>GPS Position:</b>	37° 01.980' South 143° 42.481' East	<b>Area Briefing:</b>	30
<b>WAC Chart:</b>	Hamilton (3469)	<b>ALA Code:</b>	YMBU
<b>Owner/Operator:</b>	Central Goldfields Shire Council (03) 54610610, <a href="mailto:mail@cgoldshire.vic.gov.au">mail@cgoldshire.vic.gov.au</a>		
<b>Strip Directions:</b>	06-24	17-35	
<b>Strip Lengths:</b>	600 M	1040 M	
<b>Strip Surface:</b>	Unsealed	Sealed	
<b>Windsock:</b>	Yes		
<b>Strip Markers:</b>	White cones and gable markers, runway numbers, centre line, piano keys		
<b>Lighting:</b>	Pilot Activated Lighting - RWY 17-35 - VHF 119.1, TWY blue edge lighting		
<b>Fuel:</b>	Nil		
<b>Procedures And Remarks:</b>	CTAF-AFRU 119.1. Melbourne Centre 126.8 (in the circuit). HF 3461/6565/8822. Beware of birds, kangaroos and other animals. Caution: depending on their position on the aerodrome, aircraft may not be visible to each other on the ground. Avoid overflying the town, right circuits runway 17 and 24. Circuit training not permitted 2200-0700 LMT. Permission required prior to use. Cross check details with ERSA.		